Operation instructions

1. Install the battery;

2. Press "READ" to boost, Press "FT/M" to toggle the desired unit modes

(feet ,meters);

3.Align the product to the surface to be vertical, press READ for   measuring, if you

need to   plus the measured lengths, press "+/=" to storage the first measured datas.,

press "Read" again for second measurement, press "+/=" again the sum is shown on

the bottom.

4.Press square or cubic graph buttons, measure the required length according to the

displayed icon, the product will automatically display the square or cubic values after

all the required lengths are measured,

5.If you need to plus the results of step 4, press "MEN INPUT" to storage the

measured square or cubic values, then press square or cubic graph button, press "+/="

after a new set of values to be measured, press   "MEN INPUT"   again, then press

"+/=" again to obtain the sum of two set data.

6. The measurement is completed, power off, remove the batteries, and keep the tool

well.

Care and handling:
1. The laser tape is a precision instrument which must be handled with care.
2. Avoid shock, vibrations and extreme heat.
3. Avoid dust and water, which may obstruct the lens. If needed, use a soft cloth or cotton swab
    and glass cleaner to clean the lens.
4. Keep the laser tool dry and clean.
5. Check battery regularly to avoid deterioration.
6. Remove battery if the laser tool is to be stored for an extended period of time.