

Model	Outline Drawing	Features/ Individual Specification																																					
H901-20E1-00D/0CD	SHAFT SHOWN IN FULL C.C.W. POSITION	P.C.B. MOUNTING HOLE DETAIL P.C.B T=1.6																																					
H901-40E1/40E3-00D/0CD	SHAFT SHOWN IN FULL C.C.W. POSITION P.C.B. MOUNTING HOLE DETAIL P.W.B T=1.6 <table><tr><th>M</th><th>L</th><th>10</th><th>12.5</th><th>15</th><th>17.5</th><th>20</th><th>22.5</th><th>25</th><th>18.5</th><th>30</th><th>18</th></tr><tr><td>E1</td><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>E3</td><td>7</td><td>F</td><td>4</td><td>6</td><td>7</td><td>7</td><td>12</td><td>12</td><td>12</td><td>7</td><td>14</td><td>7</td></tr></table>	M	L	10	12.5	15	17.5	20	22.5	25	18.5	30	18	E1	5											E3	7	F	4	6	7	7	12	12	12	7	14	7	P.C.B. MOUNTING HOLE DETAIL
M	L	10	12.5	15	17.5	20	22.5	25	18.5	30	18																												
E1	5																																						
E3	7	F	4	6	7	7	12	12	12	7	14	7																											
H902-20E1/20E3-00D/0CD	SHAFT SHOWN IN FULL C.C.W. POSITION	P.C.B. MOUNTING HOLE DETAIL P.C.B T=1.6 <table><tr><th>L</th><th>F</th><th>M</th></tr><tr><td>15</td><td>7</td><td>5</td></tr><tr><td>20</td><td>12</td><td>7</td></tr><tr><td>15</td><td>6</td><td>7</td></tr><tr><td>20</td><td>6</td><td>7</td></tr></table>	L	F	M	15	7	5	20	12	7	15	6	7	20	6	7																						
L	F	M																																					
15	7	5																																					
20	12	7																																					
15	6	7																																					
20	6	7																																					
H901-40-00D	SHAFT SHOWN IN FULL C.C.W. POSITION	P.C.B. MOUNTING HOLE DETAIL																																					
H902-40-00D	SHAFT SHOWN IN FULL C.C.W. POSITION	P.C.B. MOUNTING HOLE DETAIL																																					