

## Our production line has the model:

Various types of basic parameters:

<b>Item</b>	<b>Diameter of screw (mm)</b>	<b>L/D ratio</b>	<b>Speed of screw (r/min)</b>	<b>Driving power (KW)</b>	<b>Max output of production (kg/h)</b>	<b>Weight (kg)</b>
150mm 20D (vacuum)	150	20:1	0-45	160	1000	6500
150mm 16D	150	16:1	0-45	132	800	6500
120mm 20D (vacuum)	120	20:1	0-50	110	700	5200
120mm 16D	120	16:1	0-50	110	600	5200
90mm 20D (vacuum)	90	20:1	0-55	55	320	3200
90mm 16D	90	16:1	0-55	55	280	3200
75mm 20D (vacuum)	75	20:1	0-55	37	160	1200
75mm 16D	75	16:1	0-55	37	140	1200
50mm 12D	50	12:1	2-70	7.5	50	600