


User Manual

Overview



Battery Change

56.8

When this icon is displayed on the display screen Insufficient electricity and need to replace the new battery.

Use hand or coin reverse clockwise battery cover 45 degree battery cover can be removed, a section of the No. five AA battery negative, positive pole, put out, then cover the battery, clockwise rotation 45 degrees.

How to Use

- 1 Power On: Press the ON/OFF button.
- 2 Calibration: Open the standard board box, places the instrument survey mouth the black standard board. Turning the Calibrate knob and causes the display monitor the reading to conform to the black standard board demarcation value.
- 3 Checkout: Put the instrument calibrated to the standard board box the white ceramics work panel. The value that the display screen shows should not be greater than the difference of white pottery board at this moment 1.2Gu.
- 4 Measurement: Put the instrument onto the object, then the reading that display screen shows gloss value.
- 5 Power Off: Press the ON/OFF button manually or power off in 3 minutes automatic.

Parameter

Model	Glossmeter	Spec.	Single 60°
Range	0~99.9Gs 100~999Gs	Error	±1.2Gs
Power	One AA alkaline battery	Measure Spot	14x28mm
Condition	Temp.0~40℃ Humidity ≤85%	Size	110x32x64mm
Standard board Size	67x46x13mm	Weight	180g

List

- 1 Gloss meter
- 2 Standard board box
- 3 User Manual
- 4 Certification
- 5 Lens cloth
- 6 EVA Portable Pack sets,
- 7 outside Paper Pack

Attention

- The measurement unit consists of sensitive optical and elec-tronic precision parts. Prevent it from being dropped or bumped or jostled!
- Do not hold the unit by the measurement aperture. You should not allow any foreign objects to get into this opening.
- Should prevent the strong light from penetrating directly while using otherwise influence the accuracy of measuring.
- Sample preparation must according to the correlative standard.
- Avoid prolong high relative humidity and do not allow water to from condensation(see Technical data).
- Protect the measuring unit from moisture, chemicals and cor-rosive vapors.
- The holder and the unit housing are resistance to many so-lvents. However, we cannot guarantee resistance to all chemicals. You excessive dirt and dust, use ethanol or cleaning alcohol. For cleaning alcohol. Do not use any acetone!
- Please note that batteries are special refuse and shall not be disposed of together whit household refuse.

Service

This instrument or part has one year limited warranty. Under normal behavior in service any because the instrument itself quality question causes the breakdown.This company free services or the replacement for you. Following several kind of situations outside free maintenance scope:

- The instrument depreciation, falls bumps, the outer covering has falls the mark obviously.
- The instrument the liquid immersion, the corrosion, as well as the battery flows the damage which the fluid creates.
- The user turns on the instrument arbitrarily, the product namely loses the maintenance.