



6.To avoid arcing issue, The adaptor start to power supply after connector mated fully.



Packing Special
0=PE Bag
A=Tray
T=Tube
R=Reel

2.54mm 4Pins Pogo pin L=15.0