




D	M1.4	M1.6	M2	M2.5	M3	M4	M5	M6	M8	M10	M12	M16	M20
P	0.3	0.35	0.4	0.45	0.5	0.7	0.8	1	1.25	1.5	1.75	2	2.5
dk	2.6	3	3.8	4.5	5.5	7	8.5	10	13	16	18	24	30
K-max	1.4	1.6	2	2.5	3	4	5	6	8	10	12	16	20
K-min	1.26	1.46	1.86	2.36	2.86	3.82	4.82	5.7	7.64	9.64	11.57	15.57	19.48
t	0.6	0.7	1	1.1	1.3	2	2.5	3	4	5	6	8	10