

Technical drawing of a long-sleeved jacket with dimension lines A through Q. The drawing shows the front view of the garment. Key dimensions include: A (Total length), B (Total width), C (Sleeve length), D (Body length), E (Neck width), F (Neck circumference), G (Collar height), H (Cuff width), I (Pocket width), J (Pocket height), K (Pocket depth), L (Pocket position), M (Waist width), N (Pocket width), O (Pocket height), P (Pocket position), Q (Waist width), R (Waist width), and S (Waist width).

Description	Dim.	Size (cm)							Tolerance (cm)
		XS	S	M	Lg.	XL	2XL	3XL	
Body length (shoulder to bottom)	A	100	105	110	115	120	125	130	+/-2
Waist ¹	B	55	58	63	65	67	70	72	+/-2
Arm length	C	52	55	58	62	64	65	65	+/-2
Shoulder to armpit	D	26	26	27	28	29	29	30	+/-2
Collar to shoulder	E	15	17	20	22	23	24	25	+/-2
Collar width	F	21	21	21	21	21	21	21	+/-2
Collar depth	G	8.5	8.5	8.5	8.5	8.5	10	10	+/-2
Cuff length	H	6	6	6	6	6	6	6	+/-2
Pocket width	I	17	17	17	17	17	17	17	+/-2
Pocket height	J	18	18	18	18	18	18	18	+/-2
Distance from side to pocket	K	3	4	5	6.5	7.5	8.5	9.5	+/-2
Distance from bottom to pocket	L	28	31	35	40	44	49	53	+/-2
Distance in b/w Buttons	M	15	15	15	15	16	16	16	+/-2
Upper Pocket Width	N	15	15	15	15	15	15	15	+/-2