

2. Technical parameters

Model	DCS-ZW-50
Weighing range(kg)	10-99
Value(g)	10
Weighing accuracy	0.2%F/S
Weighing speed (bag/h)	180-220
Working condition and power supply	Relative humidity less than 90% AC 200V 50HZ
Air and power consumption	1.0KW 0.4-0.8Mpa air compression 1m3/h
All using top brand parts.	