

Model	Voltage	No Load		At Maximum Efficiency				Stall	
		Current	Speed	CUrrent	Speed	Torque	Output	Current	Torque
	V	A	RPM	A	RPM	g.cm	W	A	g.cm
FF-050SH-10131V	3.7	0.06	6500	0.25	3800	10	0.3	0.35	25
FF-050SH-1390V	3	0.08	8100	0.45	4900	10	0.5	0.8	35
FF-050SH-1947V	2.4	0.18	12000	0.48	10800	5	1	1.8	45