


China National Nonmetallic Mineral Products Quality Inspection Test Center


Test Report

National Nonmetallic Quality Test (X) Word No. (13538)

Total 2pages page 1st

Product Name	Brake Pad for Automobile	Spec.	04465-35290
		Product No.	—
Consign Company	Yiwu Bro Auto Accessories Factory	Test Category	Consign
Address	Room 1015, Block B Wealth Building, No.1188 Chouzhou North Road, Yiwu City Zhejiang Province China	Received Date	Nov 26, 2013
Manufacture	—	Test Date	Dec 2, 2013
Quantity	1	Consigner	Mingxian Dai
Test Method	NM/QRD/MB05:2011	Test Item	Asbestos Mineral Qualitative Analysis
Test Equipment	XRD	Sample Appearance	Brake Pad (See Sample's Picture)
Test Result	<p>This sample has not been discovered the asbestos mineral by X-ray diffraction analysis.</p> <p>Blank hereinafter</p> <p>(The test Seal for report)</p> <p>Countersign date Dec 4, 2013</p>		
Remark	Only be responsible for received sample.		

Approval: 

Checked By: 

Main Tester: 